

## **Analysis of the Destructive Winds in the Tallong/South Marulan region on December 1, 2020**

Destructive winds occurred over the Tallong/South Marulan regions on December 1, 2020 which caused considerable damage and loss of power. In this report there will be an analysis of the observed meteorology, photographic evidence of the damage and a preliminary interpretation of the possible causes.

### **The prevailing weather data on December 1, 2020**

On December 1, 2020 at around 1600 AEST, the Tallong/South Marulan region was hit by extreme wind conditions. There was only anecdotal evidence that the maximum wind speeds during this event were in the vicinity of 160 km/hr. So far this observation cannot be supported by the weather measurements at several stations in the region. In Figure 1 there are wind speed data taken from the weather stations (Gunlake and Peppertree Quarries [10 m] and 467 Mulwaree Dr., Tallong [2 m]) which show much lower speeds. At the Boral South Marulan weather station the maximum wind speed was  $17.3 \text{ ms}^{-1}$  (62.25 km/hr) in the hour prior to 1600 AEST. A stronger maximum wind speed of 108 km/hr ( $30 \text{ ms}^{-1}$ ) was observed at about 1.8 m, 546 Caoura Rd, Tallong (Figure 2). In general the higher altitude above the ground the higher wind speed, with the standard height for Bureau of Meteorology station wind measurements being 10 m. Even so the wind damage evidence to be discussed, together with overseas studies suggests that the wind speeds on this occasion were indeed closer to the anecdotal observations.

Other data are available from the Bureau of Meteorology weather radar observations. In Figure 3 the rain radar image at 1704 AEDT (1604 AEST) shows a patch of intense precipitation over the Tallong/Marulan area. In fact during this event the rain was of short duration with typical 10-15 minute amounts of only 0.8-8.5 mm. The Doppler wind radar image taken at 1704 AEDT is seen in Figure 4. In this case there is a line of intense wind speeds near the extreme scale of 90 km/hr towards the radar (dark blue shading) following the line of the rain patterns in Figure 3. An animated sequence of both the rainfall and Doppler radar images during this event (from Weatherzone) will be available on the TCFG website under the Weather Menu.

### **Evidence of the Destruction**

There was extensive damage across the Tallong/Marulan region in the form of thousands of large trees (mainly eucalypts) being uprooted, snapped off and twisted and power lines brought down with significant electricity outages. Great swathes of trees were knocked down at the end of Longpoint Road, Tallong and into the entrance of Morton National Park (MNP) there. Some of the tree damage on the farm at 432 Longpoint Road can be seen in Figure 5. These images were taken of about a 100m wide path of tree destruction through a forest on the farm bordering the MNP. Not only were trees snapped but huge gum trees uprooted. Elsewhere on the farm and across Longpoint Road there were other significant tree uprootings (Figure 6). Inside the MNP to the left of the entrance can also be seen trees snapped half way up and a tree trunk twisted and bent (Figure 7). Further SW on Greenhills Road, Marulan there was also evidence of trees being snapped and forest destruction (Figure 8). The overall impression is of small areas of intense destruction.

Drone photos on the Longpoint Rd farm taken some 13 months after this destructive event show consistent directions of the tree downfalls. These can be seen in Figures 9-11. A drone flyover of the affected area near the end of the bitumen section of Longpoint Road can be seen at <https://youtu.be/QuGkKW9sISY>

### **Overseas and other studies of forest destruction due to extreme winds**

The destruction observed in Tallong/Marulan on December 1, 2020 seems to be a result of a series of concentrated downbursts from a thunderstorm moving across the region. " Microbursts are small — less than 4 km across — and short-lived, lasting only five to 10 minutes, with maximum wind speeds sometimes

exceeding 100 mph." (NSSL 2021). In Figure 12 from this report there is an overseas example of forest destruction due to a microburst. It is suggested that the tree destructions in Figure 5 and Figures 9-11 are similar to that in Figure 12. Johnson (2018) reported " Microbursts are often mistaken for tornadoes as both can have damaging winds, a loud "roaring sound" from high winds, and "twisted" off tree damage."If it's a tornado, that damage is going to be in different directions. For a microburst wind, chances are everything is going to be in the same direction, so trees are going to be laying down in the same direction," said Chief Meteorologist Chris Bailey." The observation of possible "twisting" associated with a microburst is consistent with the observations in Figure 7 and trees lying in the same direction consistent again with Figure 5 and Figures 9-11. Other reports on microbursts can be seen at Pedersen (2016) and Caracena (1994). Geerts (2000) studied a climatology of strong short-lived wind gusts (microbursts) in NSW and found that above 21 ms<sup>-1</sup> the frequency of occurrence fell by 50% in each 3 ms<sup>-1</sup> increment.

### **Conclusions:**

While the maximum measured wind speed associated with the tree damage on December 1, 2020 was 108 km/hr the photographic evidence suggests that in those areas of maximum damage the wind speeds were much higher, possibly even up to the anecdotal value of 160 km/hr; the relatively narrow swathes of destruction meant the extreme winds may have missed the recording station locations. The tree damage is also consistent with being the result of a series of microbursts or extreme downdrafts associated with the thunderstorm which crossed the region.

Geoff Clark

January 2022

Email: geoff\_run@hotmail.com

### **Acknowledgements:**

Many thanks for the weather data are due to Sharon Makin, Boral, Geoff Kettle, Gunlake Quarry, Simone Donaldson and Andrew Miskelly from Weatherzone.

### **References:**

Caracena, F. Forecasting Microbursts & Downbursts. Taken from "Windshear Revisited by Capt. William W. Melvin (from Air Line Pilot Magazine, Nov. 1994, excerpted from SAE Paper 901995)

Geerts, B. 2000: Estimating downburst-related maximum surface wind speeds by means of proximity soundings in New South Wales, Australia. July In press?

Johnson, C. 2018: WKYT - What are microbursts and why can they cause so much damage?  
<https://www.wkyt.com/content/news/What-are-microbursts-and-why-can-they-cause-so-much-damage-487526741.html>

NSSL 2021: Severe Weather 101 - Damaging Winds. National Severe Storms Laboratory.  
<https://www.nssl.noaa.gov/education/svrwx101/wind/types/>

Pedersen, T. 2016: Facts About Microbursts <https://www.livescience.com/55912-microbursts.html>




Figure 1



Figure 2

# Wollongong Radar - Rain Rate

05:00 01/12/2020 UTC to 07:00 01/12/2020 UTC

🕒	1hr	2hrs	4hrs	8hrs	12hrs	18hrs	24hrs	36hrs	48hrs
🌐	64km 🌧️	128km 🌧️	256km 🌧️	512km 🌧️	128km 📶	HD 🌧️			

[Help / More Information](#)  
[Top activity days](#)


This page is for personal and academic use only. Upgrade




05:04pm 01 Dec 2020 AEDT +11:00

06:04 01 Dec 2020 UTC +00:00

## Intensity Timeseries



## Intensity Histogram



## Custom Timeframe :

2020-12-01 4pm to 2020-12-01 6pm

Timezone : Australia/Sydney (Radar Local)

[Update](#)

## Export

Visualisation (GIF)

[Create](#)

Data Pack

[Request](#)

Data packs are available that can contain a variety of processed radar data including animated GIF, mp4 video, individual composite images, rainfall estimations, custom GIS overlays and a KMZ files.

Figure 3




Figure 4



Figure 5



**Figure 6**






Figure 7



Figure 8



**Figure 9**



**Figure 10**



**Figure 11**



Figure 12 (from NSSL 2021)